



Batch Process Shortcomings:

- 70 bar pressure necessary
- maximum ~94% ee

Continuous Process Advantages:

- high pressure flow reactions are practical and safe
- continuous crystallization allows for enantiopurity upgrade to >99% ee